



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

May 14, 2013

Reviewed: PNB

Mine Name: Fox Clay	Permit Number: S/049/0077
Operator Name: Interstate Brick Company	Inspection Date: May 14, 2013
Inspector(s): Lynn Kunzler & April Abate	Time: 2:00 PM
Other Participants: Tom Nicolaysen (intern)	Mine Status: Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

The purpose of the inspection is to introduce new lead, April Abate to the site. Check the status to see if active mining has begun.

Inspection Summary:

Photos were taken to document site conditions.

No activity was observed on the site. A small mine permit was approved in 2010; however, the operator has not initiated any activity.

Conclusions and Recommendations:

Lynn recommended that a file closure letter be sent to the operator.

Inspector's Signature [Signature]

cc: Interpace Holdings, LLC

O:\M049-Utah\S0490077-FoxClay\inspections\Insp_051413.doc



View of permitted area a hill (background). Some disturbance from the Snow White mine to the south.



Closer view of the permitted area.